

Originating in Japan hundreds of years ago, rain chains were developed as a way to collect rainwater for homes without running water. The rain glides through and around the chain providing a fountain like effect with the sound of flowing water capturing and entertaining the senses. Our new design, Rainchain[®], similarly captures and entertains our visual sense.

| | US UNITS | METRIC UNITS |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| Total Weight | 24.0 oz PLY 16.0 oz PSY | 744 g PLM 542 g PSM |
| Roll Width | 52/54 in. | 132/137 cm |
| Gauge | 24 Mils | 0.61 mm |
| Fabric | Non-Woven | |
| Tensile (Minimum) | 50 x 50 lb _f | 222 x 222 N |
| Tear (Minimum) | 25 x 25 | |
| WA Spec | WA-W-101, Type II | |
| Fire Testing | NFPA 101 [®] Life Safety Code [®] NFPA255 (UL723, CAN S102M) Tunnel Test ¹ Class A Rating NFPA 286 Corner Burn Test ² Meets requirements for Flame Spread, Smoke Developed and Flashover | |
| Repeat | Vertical | 1.3 in. 3.3 cm |
| | Horizontal | 1.3 in. 3.3 cm |
| | Nominal Pattern Width | 50.7 in 129 cm |
| | Match Information | Match Pattern, Reverse Hang |
| | 1 When applied to GRC Board with A-848-B adhesive | 2 When applied to 5/8" Type-X gypsum board with A-848-B adhesive |

Available in 17 Colorways

- RC24-46 Basin
- *RC24-43 Bronze
- *RC24-66 Cardinal
- RC24-02 Cumulus
- *RC24-72 Droplet
- *RC24-99 Fountain
- RC24-98 Hematite
- RC24-28 Kusari Doi
- RC24-23 Pebble
- *RC24-95 River Rock
- RC24-15 Solitude
- RC24-90 Statuary
- *RC24-54 Stepping Stone
- *RC24-51 Sundial
- *RC24-87 Trellis
- *RC24-81 Verdigris
- *RC24-42 Wind Chime

* These decorative metallic wallcoverings should only be cleaned with mild ingredients such as soap, detergent and water. Stronger, more alkaline household cleaners have the potential to damage the surface of the wallcovering along with excessive scrubbing.